

Weird Surface quality

Pegasus touch with recent laser diode upgrade
Super VAT (goes worse on regular vat)

All optical surfaces were cleaned

Realigned galvos and calibrated laser


Tested on White resin, blue castable resin.

All resin used was well mixed and from unopened bottles


Retina 1.0579.20694

Kerf and thermal time = Defaults


White resin 0.1mm with lot of flakes




Castable resin 0.1mm with a Little less flakes
Note, the firsts layers comes fine




Castable resin 0.1mm with a Little less flakes
Note, the firsts layers comes fine



Castable resin and White resin 0.1mm
results after isopropyle bath



Castable resin and White resin 0.1mm
results after isopropyle bath



Castable resin 0.05mm
results right after finished print

